

20




FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 4




FIG. 5A




FIG. 5B




FIG. 6




FIG. 7







FIG. 8






FIG. 10A




FIG. 10B




FIG. 11




FIG. 12

36

$i \backslash j$	-1	0	1
0	$h_{0,-1}$	$h_{0,0}$	$h_{0,1}$
1	$h_{1,-1}$	$h_{1,0}$	$h_{1,1}$
2	$h_{2,-1}$	$h_{2,0}$	$h_{2,1}$
$\vdots$	$\vdots$	$\vdots$	$\vdots$
N-1	$h_{N-1,-1}$	$h_{N-1,0}$	$h_{N-1,1}$

FIG. 13

37

$i \backslash j$	M1	...	-1	0	1	...	M2
0	$g_{0,M1}$	...	$g_{0,-1}$	$g_{0,0}$	$g_{0,1}$	...	$g_{0,M2}$
1	$g_{1,M1}$	...	$g_{1,-1}$	$g_{1,0}$	$g_{1,1}$	...	$g_{1,M2}$
2	$g_{2,M1}$	...	$g_{2,-1}$	$g_{2,0}$	$g_{2,1}$	...	$g_{2,M2}$
$\vdots$	$\vdots$	$\vdots$	$\vdots$	$\vdots$	$\vdots$	$\vdots$	$\vdots$
N-1	$g_{N-1,M1}$	...	$g_{N-1,-1}$	$g_{N-1,0}$	$g_{N-1,1}$	...	$g_{N-1,M2}$

FIG. 14




FIG. 15






FIG. 16




FIG. 17A




FIG. 17B (PRIOR ART)




FIG. 18A




FIG. 18B (PRIOR ART)




FIG. 19A




FIG. 19B (PRIOR ART)




FIG. 20




FIG. 21




FIG. 22




FIG. 23 (PRIOR ART)






FIG. 24 (PRIOR ART)